

Nut type	SH	=	Miniature screw, axial play
	SX	=	Universal screw, axial play
	SN	=	Precision screw, axial play
	TN	=	Precision screw, backlash elimination
	PN	=	Precision screw with optimal rigidity
	TND	=	Precision screw, backlash elimination, DIN nut
	PND	=	Precision screw with optimal rigidity, DIN nut
	SL	=	Long lead screw, axial play
	SLD	=	Long lead screw, axial play, DIN nut
	TL	=	Long lead screw, backlash elimination
TLD	=	Long lead screw, backlash elimination, DIN nut	

Nominal diameter x Lead

Hand R = Right L = Left (on request)

Threaded length / Total length, mm

Lead precision : G9, G7, G5

Nut orientation

Threaded side or flange of nut towards shorter (**S**) or longer (**L**) machined end of shaft. In case of same end machining : (-)

Machined end combination

See page 22

Required lengths for :

AA - SA (both sides)

See page 22

WPR :
with wipers
NOWPR :
without

SN 32 x 5 R 330/445 G7 L-HA+K **/ WPR**